

SAFETY RULES

Aluminium Dunkerque Smelter





- 1. Wearing your EPI
 - Safety shoes
 - Protective workwear with closed collar
 - High visibility safety vest
 - Helmet equipped with a visor and a neck protector
 - Safety goggles
 - Hearing protection (depending on the sector)
 - Respiratory protection (depending on the sector)
 - Gloves





2. Always stay with your guide



- 3. Do not take with you (leave in the cloakroom)
 - Watches
- Magnetic strip cards (credit cards etc)
- Rings
- Lighters
- Photo cameras

4. Pregnant women and people with a heart device or insulin pump are not allowed to visit the site

5. Use the pedestrian walk ways



6. Do not use your cellular phone





7. Hold the handrail while using the stairs











8. Do not stop in the areas of passing machines. They always have the right of way.



9. Never touch any solid aluminium as there is no way to tell if it is hot or cold.







Thanks!

In case of doubt, please ask!

